

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

L P C F C O 5 5 C  
(1) (8) (9)

INSPECTION REPORT - SITE INVENTORY NO. 07702002

(11) (18)

Co. - L.P.C.

Region #

Date 050780

(19)

(20)

(25)

Letter Sent (Yes or No) N

(26)

Weather 75° sunny day

Inspector P C

(27)

(29)

Samples Taken: Yes ( ) No (X) Time: From 05:25 pm  
Ground Water( ) Surface( ) Other( ) To 06:00 pm  
Photos Taken: Yes (X) No ( ) Interviewed none

Previous Inspection 4/11/80 Previous Correspondence 3/17/80

Site Open: Yes ( ) No (X)

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (X) Sanitary Landfill (X) Storage ( )  
Temporarily Closed ( ) Random Dump ( ) Salvage ( )  
Closed Not Covered ( ) Other ( ) A.C.D. ( )  
Closed and Covered ( ) Quantity Received Daily(1-6) 3  
(30)

E.P.A. Permit (X)  
Variance ( )  
21(e) ( )  
Board Order ( )  
Illegal (5) ( )

SITE EVALUATION

(31)

Leachate: Ponded on site (X) 32  
Flowing on site (X) 33  
Seeping (X) 34  
Evidence of past flows (X) 35  
Observed garbage( ) refuse(X) in standing water (X) 36 X  
Flow entering surface water (5) 37  
Flow leaving site (1-3) 38  
Open Burning: Observed (5) 39  
Underground fire (5) 40  
Evidence of recent open burning (5) 41  
Insufficient fire protection equipment provided (2) 42  
Daily Cover: Not provided on previously deposited refuse (5) 43 3  
Not provided on previous operating day (4) 44 4  
Inadequate depth over entire area (3) 45  
Inadequate depth over only a portion of area (1-2) 46 2  
Intermediate Cover: Inadequate depth in portion(s)( ) or entire(X) required areas(1-3) 47 3  
Final Cover: Inadequate depth in some areas (1-3) 48  
Inadequate depth over entire area 60 days after area closure (4) 49  
None 60 days after area closure (5) 50  
Unloading not supervised (3) 51  
Refuse not deposited at toe of slope ( )  
Inadequate spreading and compacting (X)  
Insufficient operable equipment on site as required ( ) (2 ea. 2-8) 52 2  
Operational roads unsatisfactory ( )  
Blowing litter( ), dust nuisance observed( ), Odor detected( ) (1 ea. 1-3) 53  
Permit(X) Board Order( ) Violation noted (2 ea. 2-4) no cover stock p. 4 54 2  
Liquids( ) Solids( ) not permitted (5) 55  
Inadequate site restriction( ) Site concealment( ) (2 ea. 2-4) 56  
Inadequate: Shelter( ) Sanitary Facilities( ) Emergency Communications( ) (1 ea. 1-3) 57  
Scavenging by: Operator( ) Others( ) observed (1-3) 58  
Salvaging Observed( ): Improperly conducted in: Location( ) Operation( ) Storage( ) (1-3) 59  
Evidence of vectors observed ( ) (1-3) 60  
Animal feeding observed ( ) (1-3) 61

General Compliance ( )

much Improvement Needed (X)

Improvement Observed ( )

Signature of operator does not necessarily imply agreement with the above noted observations.

US EPA RECORDS CENTER REGION 5




484180

LPC-5 (Rev. 6-75-500)

Signature

Owner/Operator



Date: May 7, 1980

Time: 5:25 A.M. (P.M.)

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the Northeast



Date: May 7, 1980

Time: 5:25 A.M. (P.M.)

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the East



Date: May 7, 1980

Time: 5:30 A.M. (P.M.)

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the South Southwest



Date: May 7, 1980

Time: 5:35 A.M. (P.M.)

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the North Northwest



Date: May 7, 1980

Time: 5:40 A.M. P.M.

Photograph By:

P.C. Mann

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken  
toward the South Southeast

Date: May 7, 1980

Time: 5:40 A.M. P.M.

Photograph By:


P.C. Mann

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken  
toward the South



Date: May 7, 1980

Time: 5:42 A.M. (P.M.)

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the South Southeast



Date: May 7, 1980

Time: 5:45 A.M. (P.M.)

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the North Northeast



Date: May 7, 1980

Time: 5:50 A.M. P.M.

Photograph By:

*P.C. Moore*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the North



Date: May 7, 1980

Time: 5:55 A.M. P.M.

Photograph By:

*P.C. Moore*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the East Northeast



Date: May 7, 1980

Time: 5:57 A.M. P.M.

Photograph By:

*P.C. Mann*

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the North Northeast



Date:

Time: A.M. P.M.

Photograph By:

Location: LPC-

Co.

/

Comments: Photograph taken

toward the



Date: May 7, 1980

Time: 5:58 A.M. P.M.

Photograph By:

P.C. Mann

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the West Southwest

Date: May 7, 1980

Time: 5:58 A.M. P.M.

Photograph By:

P.C. Mann

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the West



Date: May 7, 1980

Time: 5:59 A.M. P.M.

Photograph By:

O.C. Mann

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the North

Date: May 7, 1980

Time: 5:59 A.M. P.M.

Photograph By:

O.C. Mann

Location: LPC- 077 020 02

Jackson Co.

DeSoto / Allen #2

Comments: Photograph taken

toward the Northeast

